JOHNSON UTILITIES, L

0000084428

5230 East Shea Boulevard * Scottsdale, Arizona 8 PH: (480) 998-3300; FAX: (480) 483-7908

50

ORIGINAL

April 29, 2008

Mr. Brian Bozzo Arizona Corporation Commission 1200 W. Washington Street Phoenix, Arizona 85007

RE: Johnson Utilities, L.L.C.: Compliance with Decision No. 65840, 64062

RE: Annual Water and Wastewater Compliance with ADEQ regulations.

WS-02987A-99-0583; WS-02987A-00-0618; W-02234A-00-0371; W-02859A-00-0774;

W-01395A-00-0784

Dear Mr. Johnson:

Pursuant to the above mentioned decisions, Johnson Utilities hereby submits this compliance filing in accordance with the Commission's orders. Enclosed please find the Arizona Department of Environmental Quality's (ADEQ) Compliance Status letters for the Pecan, San Tan, Section 11, and Anthem Waste Water Treatment Plants attached hereto as Attachments 1, 2, 3, and 4 respectively. Also, enclosed please find the ADEQ's Drinking Water Compliance Status Reports for System 11-128 and 11-136 attached hereto as Attachments 5 and 6 respectively. All 6 letters indicate the water & sewer facilities are in full compliance with ADEQ regulations. Should you have any questions or concerns, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Arizona Corporation Commission DOCKETED

APR 29 2008

DOCKETED BY M

Sincerely,

Brian P. Tompsett

Johnson Utilities, LLC

Cc: Docket Control

Richard Sallquist, Sallquist, Drummond & O'Connor

ACCEPTED 3:5

for Brian P. Tompsety





1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.adeq.state.az.us

March 10, 2008

Johnson Utilities Company Mr. Daniel Hodges 5230 E. Shea Blvd, Suit 200 Scottsdale, AZ 85254

RE: Compliance Status for Pecan Water Reclamation Plant, inventory number 105324, Permit number 41570.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Pecan Water Reclamation has Aquifer Protection Permit number 41570.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility **is in compliance** based on the current information that is available to ADEQ. No enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II Water Quality Data Unit Water Quality Compliance Section FAV@AZDEQ.GOV





1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.adeq.state.az.us

March 10, 2008

Johnson Utilities Company Mr. Daniel Hodges 5230 E. Shea Blvd, Suit 200 Scottsdale, AZ 85254

RE: Compliance Status for San Tan WWTP, Inventory number P-105325,

Place Id: 18584, Permit number: 34792.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that San Tan WWTP has Aquifer Protection Permit number 34792.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility **is in compliance** based on the current information that is available to ADEQ. No enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II Water Quality Data Unit Water Quality Compliance Section FAV@AZDEQ.GOV



1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.adeq.state.az.us



April 28, 2008

Johnson Utilities Company Mr. Daniel Hodges 5230 E. Shea Blvd, Suit 200 Scottsdale, AZ 85254

RE: Compliance Status for Johnson Utilities section 11 WWTP, Inventory number P-103081, Place Id: 142, Permit number: 35634.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Section 11 WWTP has Aquifer Protection Permit number 35634 issued on 10/4/2006.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility **is in compliance** based on the current information that is available to ADEQ and no enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II Water Quality Data Unit Water Quality Compliance Section





1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.adeq.state.az.us

March 10, 2008

Johnson Utilities Company Mr. Daniel Hodges 5230 E. Shea Blvd, Suit 200 Scottsdale, AZ 85254

RE: Compliance Status for Anthem and Merrill Ranch WRP, inventory number 105646, Permit number 36819.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Anthem and Merrill Ranch WRP has Aquifer Protection Permit number 36819 issued on 6/30/2006.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility **is in compliance** based on the current information that is available to ADEQ. No enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II Water Quality Data Unit Water Quality Compliance Section FAV@AZDEO.GOV

Arizona Department of Environmental Quality

Drinking Water Monitoring and Protection Unit 1110 W. Washington Street, 5415B-2 Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name:	Johnson Util	ities	
Public Water System ID #:	11-128		
Public Water System Type:	[X] Community [] No	n-transient Non-community	[] Transient Non-community
Overall Compliance Status:	[X] No Major Deficien	cies [] Major Deficiencie	es
Monitoring and Reporting Status: Comments: None	[X] No Major Deficien	cies [] Major Deficiencie	es
Operation and Maintenance Status Comments: None	: [X] No Major D	Deficiencies [] Major De	ficiencies
Major unresolved/ongoing operation unable to maintain 2 cross connection/ba treatment deficiencie certified operator	Opsi ckflow problems	ciencies: [] inadequate storage [] surface water treatment [] approval of construction [] other	
Date of last inspection / sanitary surv	ey: <u>7-6-07</u>		
Administrative Orders: Is an ADEQ administrative order in electric comments: None	ffect? [] Yes	[X] No	
System information:			
Number of Entry Points to the Distrib	ution System <u>8</u>	Number of Source	s <u>12</u>
Population Served 47947 Service	Connections 17124	Initial Monitoring Y	ear <u>2000</u>
Evaluation completed by: <u>Donna (</u> Phone: <u>602-771-4641</u>	Calderon, Manager, C	Drinking Water Monitoring	g and Protection Unit

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

Date: March 21, 2008

Arizona Department of Environmental Quality

Drinking Water Monitoring and Protection Unit 1110 W. Washington Street, 5415B-2 Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name:	ANTHEM AT MERRILL RANCH
Public Water System ID #:	<u>11-136</u>
Public Water System Type:	[X] Community [] Non-transient Non-community [] Transient Non-community
Overall Compliance Status:	[X] No Major Deficiencies [] Major Deficiencies
Monitoring and Reporting Status: Comments: None	[X] No Major Deficiencies [] Major Deficiencies
Operation and Maintenance Status Comments: None	s: [X] No Major Deficiencies [] Major Deficiencies
Major unresolved/ongoing operation [] unable to maintain 2 [] cross connection/ba [] treatment deficiencie [] certified operator	20psi [] inadequate storage ackflow problems [] surface water treatment rule
Date of last inspection / sanitary surv	vey: <u>6-22-07</u>
Administrative Orders: Is an ADEQ administrative order in e Comments: None	ffect? [] Yes [X] No
System information:	
Number of Entry Points to the Distrib	nution System 1 Number of Sources 2
Population Served 804 Service	e Connections 300 Initial Monitoring Year 2008
Evaluation completed by: Donna (Phone: 602-771-4641) Date: March 21, 2008	Calderon, Manager, Drinking Water Monitoring and Protection Unit

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.